

U.S. Senate
Desk Description and Condition Report

Desk No : **66.00000.025**

Paper Label No.(on shelf bottom): 25

Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 25, 25, XXX / Top: 25 (stamped), 21 (crayon) / Drawer Bottom: outside - 3 (pencil) ; inside - 25 (pen) / Drawer Back: asst. numbers / Bottom of Shelf (other than paper label): 18, 18 or 81 (pencil) / Drawer Blade: 25 (pencil) / Inkwell: 25 (pencil), 2 (pencil)

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 3/8	32 1/4		
Width (front)	27 13/16	26 3/4	25 11/16	
Width (rear)	27 3/16	26 1/16	25 1/16	
Depth	20	20 1/4	19 3/16	9 1/8

* Note: Dimensions do not include "booster" blocks added to feet or writing top.

Woods

Primary:	Mahogany <input checked="" type="checkbox"/>
	Mahogany veneer <input checked="" type="checkbox"/>
	Rosewood veneer <input type="checkbox"/>
Other Wood (specify): _____	

Character of case mahogany:	Plain <input type="checkbox"/>
	Ribbon <input checked="" type="checkbox"/>
	Mottled <input type="checkbox"/>
	Crotch <input type="checkbox"/>
	Other <input type="checkbox"/>

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				✓	
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior	✓	✓			
Drawer Front	✓				

Construction Details

Leg:

Wood Type	rosewood crossband	other crossband	no crossband
mahog. veneer			
solid mahogany			✓
other: _____			

Foot construction:

1-part ☒2-part ☐5-part ☐

Other: _____

Cockbead width on bottom of drawer front:

Narrow ☐Full width ☒

Double bead on edge of leg:

Bead: Thick ☐Thin ☒

Leg Thickness: 1 3/16 "

Opening in original top for inkwell:

Yes ☐No ☒

Shape of cross-stretcher edges:

Rounded ☐Rectangular ☒

Roundels:

Single piece ("yo-yo" form) ☐Applied boss ☒

Spindle type:

Thick

Thin

Other

Number

9

1

Inset distance of single bead on desk back panel:

Side: 15/16"

Top: 1 1/4"

Bottom: 1 1/4"

Joinery of lower drawer blade to case sides:

single dovetail ☐2 dovetails ☐3 dovetails ☐lap joint ☐

other: Blind

No. of Glue Blocks

Case

Stretch'r

Shelf

Original/Old

2

New/Recent

7

Missing

Shelf molding applied:

Yes ☐No ☒Interior case-side flush with corner block? Yes ☒No ☐

Width of drawer-opening offset

Right : 1/2"

Left : 1/2"

Condition of Desk

Structure

Previous breaks in structural elements: Yes ☐
(shown on schematic)

No ☒

Current split or broken elements: Yes ☒
(shown on schematic)

No ☐

Other loose or damaged joinery: Yes ☐
(describe in narrative)

No ☒

Damage to drawer front: Extreme ☐
Moderate ☒
Minor ☐

Drawer lock: relocated on face Yes ☒

Drawer lock: resized on inside Yes ☒

Cockbead on drawer front: Damaged ☒
(show on schematic)

Missing ☐

Loose ☐

Replacements ☐

Replaced drawer-side runners: Yes ☐

No ☒

Replaced case-side runners: Yes ☐

No ☒

Drawer bottom pieced-out at back edge: Yes ☒

No ☐

Wear on Feet	Extreme	Moderate	Minor
Front	✓		
Rear			✓

Number of loose spindles: No: 0

Number of replaced spindles: (show on schematic) No: 1

Replaced veneers and cross-banding: Yes ☐
(show on schematic)

No ☒

Missing veneers and cross-banding: Yes ☒
(show on schematic)

No ☐

Delaminated/loose veneers & cross-banding: Yes ☐
(show on schematic)

No ☒

Shelf supports: Original/old ☒
New/recent ☐
Missing ☐

Spindle support board in case: Yes ☐

No ☒

Finish

Age	Excellent	Good	Fair	Poor
New			✓	
Old				
Unk.				

Note: Describe finish problems in narrative.

Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)	✓		✓
Knob (R)			✓

Toe cap size:

Right toe: 9A

Left toe: 9A